

2015 URFC Roads and Water Monitoring Report

Road Maintenance Activities

Road maintenance that occurred outside of active THPs was limited to the M&M road and the WRP road (see table below). As a general prescription, all mainline ridgetop roads are monitored following a significant (> 2.5" in 24 hrs) rainfall event.

	2015
New Road Construction (ft)	11,372
Roads Decommissioned (ft)	0
Road Surface Maintenance (mi)	2
Roadside Mowing (mi)	2

Environmental Enhancement

Project Name	Type	Number of Sites	Cubic Yards of Sediment	Total Treatment Costs
SF Usal Coho	LWD	54	0	\$86,495
Standley Cr Sediment	Road Decommissioning	29	14,647	\$194,391
Standley Cr LWD	LWD	15	0	\$57,845

Water Drafting

Site Name	Watercourse Class	Amount Diverted (Acre-Feet)
M&M 2	II	0.736533
Hales Grove Rd	II	0.589226
MM Road Tank	II	0
Piercy Cr Xing	I	0
WRP	II	0.736533
Road 4100 Tank	II	0
Hales Grove Tank	II	0.589226